



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Re Patent of:

Kikuo NAITO, et al.

Appln. No.: 09/409,347

Filed: September 30, 1999

For: INFORMATION PROCESSING
 APPARATUS ENABLING ELECTRONIC
 WATERMARKING, AND
 COMMUNICATION NETWORK
 CONNECTABLE TO SUCH INFORMATION)
 PROCESSING APPARATUS

) : Examiner: Charles Kim
) : Group Art Unit: 2623
) : Patent No.: 6,980,668 B1
) : Issued: December 27, 2005
) : April 18, 2006

Commissioner for Patents
 P.O. Box 1450
 Alexandria, VA 22313-1450

**Certificate
 APR 21 2006
 of Correction**

Attention: CERTIFICATE OF CORRECTION BRANCH

**REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

04/19/2006 SZEWDIE1 00000110 6980668

01 FC:1811

100.00 OP

APR 21 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,



Brian L. Klock
Attorney for Patentees
Registration No. 36,570

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

BLK/lp

DC_MAIN 236935v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS

Sheet 29, Fig. 35, "RECEIVNG" should read --RECEIVING--.
Sheet 31, Fig. 37, "INVISUAL" should read --INVISIBLE-- (all occurrences).
Sheet 31, Fig. 37, "VISUAL" should read --VISIBLE-- (all occurrences).
Sheet 31, Fig. 37, "TRANSMITTING" should read --TRANSMISSION-- (all occurrences).
Sheet 31, Fig. 37, "CRIBBING" should read --CROPPING--

COLUMN 1

Line 64, "if" should read --is--.

COLUMN 12

Line 36, "meas 704." should read --means 601--.

COLUMN 13

Line 18, "is" should read --is to--.

COLUMN 17

Line 27, "is" should be deleted.
Line 66, "211, 212 213" should read --211, 212, 213--.

COLUMN 18

Line 2, "entry" should read --entry is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lip DC_MAIN 236955

→ _____

APR 21 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 64, "E:\\$pop1\\$image1.jpg" should read --E:\\$pop1\\$image1.jpg--.

COLUMN 20

Line 44, "the tag name is" should read --the tag name and is--.

COLUMN 25

Line 27, "that" should read --that were--.

Line 43, "sever 112." should read --server 112.--.

COLUMN 26

Line 2, "process this" should read --process--.

Line 13, "need" should read --need to--.

COLUMN 32

Line 29, "3405" should read --S3405--.

COLUMN 39

Line 4, "mens" should read --means--.

Line 58, "means 4032" should read --means 403--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lp DC_MAIN 236955

→

APR 21 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 48

Line 47, "this will" should read --will--.

COLUMN 49

Line 53, "ben" should read --been--.

COLUMN 51

Line 19, "case" should read --case is--.

DC_MAIN 236955v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lp DC_MAIN 236955

→

APR 21 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS

Sheet 29, Fig. 35, "RECEIVNG" should read --RECEIVING--.
Sheet 31, Fig. 37, "INVISUAL" should read --INVISIBLE-- (all occurrences).
Sheet 31, Fig. 37, "VISUAL" should read --VISIBLE-- (all occurrences).
Sheet 31, Fig. 37, "TRANSMITTING" should read --TRANSMISSION-- (all occurrences).
Sheet 31, Fig. 37, "CRIBBING" should read --CROPPING--

COLUMN 1

Line 64, "if" should read --is--.

COLUMN 12

Line 36, "meas 704." should read --means 601--.

COLUMN 13

Line 18, "is" should read --is to--.

COLUMN 17

Line 27, "is" should be deleted.
Line 66, "211, 212 213" should read --211, 212, 213--.

COLUMN 18

Line 2, "entry" should read --entry is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lip DC_MAIN 236955

→
APR 21 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 64, "E:\\$pop1\\$image1.jpg" should read --E:\\$pop1\\$image1.jpg--.

COLUMN 20

Line 44, "the tag name is" should read --the tag name and is--.

COLUMN 25

Line 27, "that" should read --that were--.

Line 43, "sever 112." should read --server 112--.

COLUMN 26

Line 2, "process this" should read --process--.

Line 13, "need" should read --need to--.

COLUMN 32

Line 29, "3405" should read --S3405--.

COLUMN 39

Line 4, "mens" should read --means--.

Line 58, "means 4032" should read --means 403--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lip DC_MAIN 236955

→

APR 21 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,980,668 B1
DATED : December 27, 2005
INVENTOR(S) : Kikuo Naito et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 48

Line 47, "this will" should read --will--.

COLUMN 49

Line 53, "ben" should read --been--.

COLUMN 51

Line 19, "case" should read --case is--.

DC_MAIN 236955v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,980,668 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) BLK/lip DC_MAIN 236955



APR 21 2006